

AD A 090938

DDC FILE COPY

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOV. ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
	AD-A090 938	
4. TITLE (and Subtitle) Phase I Inspection Report Mill Pond Dam Lake Champlain Basin, Essex County, New York Inventory No. 368		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s) George Koch		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS New York State Department of Environmental Conservation 50 Wolf Road Albany, NY 12233		8. CONTRACT OR GRANT NUMBER(s) ✓ DACW-51-79-C-0001
11. CONTROLLING OFFICE NAME AND ADDRESS New York State Department of Environmental Con- servation/ 50 Wolf Road Albany, New York 12233		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza/ New York District, CofE New York, New York 10007		12. REPORT DATE 28 August 1980
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
<p>THIS DOCUMENT IS BEST QUALITY PRACTICABLE. THE COPY FURNISHED TO DDC CONTAINED A REPRODUCE DEDICATED</p> <p>DTIC SEP 30 1980 A</p>		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety National Dam Safety Program Visual Inspection Hydrology, Structural Stability Mill Pond Dam Essex County Lake Champlain Basin		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. Examination of available documents and a visual inspection of the dam did not reveal conditions which constitute an immediate hazard to human life or property.		

Several deficiencies were noted and these should be corrected within 6 months of the date of final approval of this report. Among the actions which should be taken are refilling the cribs which are missing material, repair of displaced timbers on the downstream face, replace broken timbers, repair of the valve on the drain, and repair of the spalling concrete on the wingwall which extends downstream of the north abutment. In addition, a detailed emergency action plan and warning system should be developed.


This dam does not have sufficient spillway capacity to adequately discharge the peak outflow from one-half the PMF. The analysis indicates that the dam would be overtopped by all storms exceeding 15% of the PMF. However, the structural stability analysis indicates that the dam would be stable when subjected to the PMF storm event. Therefore, the spillway is assessed as being inadequate.

The water surface level for either the PMF or one-half the PMF would result in flow around the northern end of the concrete wingwall which extends from the abutment of the dam. An accurate topographic survey should be performed where this end around flow is likely to occur. This survey should be completed within 6 months and modifications necessary to prevent the adverse effects of this flow should be made within 12 months.

LAKE CHAMPLAIN BASIN MILL POND DAM

ESSEX COUNTY NEW YORK
INVENTORY NO N.Y. 368

6 PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM,
Mill Pond Dam (Inventory Number NY 368),
Lake Champlain Basin, Essex County,
New York.
Phase I Inspection
Report



15 DACW51-79-C-4441
12/14/80
10 George/Koch
11/28 Aug 80

NEW YORK DISTRICT CORPS OF ENGINEERS

JULY, 1980

80 10 29 0354
393970

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

Accession For

NTIS GRA&I

DTIC TAB

Unannounced

Justification

Ext.

Dist.

Dist.

A25

GP

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
MILL POND DAM
I.D. NO. N.Y. 368
LAKE CHAMPLAIN RIVER BASIN
ESSEX COUNTY, NEW YORK

TABLE OF CONTENTS

	<u>PAGE</u>
- ASSESSMENT	-
- OVERVIEW PHOTOGRAPH	-
1 PROJECT INFORMATION	1
1.1 GENERAL	1
1.2 DESCRIPTION OF PROJECT	1
1.3 PERTINENT DATA	2
2 ENGINEERING DATA	4
2.1 GEOTECHNICAL DATA	4
2.2 DESIGN RECORDS	4
2.3 CONSTRUCTION RECORDS	4
2.4 OPERATION RECORD	4
2.5 EVALUATION OF DATA	4
3 VISUAL INSPECTION	5
3.1 FINDINGS	5
3.2 EVALUATION OF OBSERVATIONS	6
4 OPERATION AND MAINTENANCE PROCEDURES	7
4.1 PROCEDURE	7
4.2 MAINTENANCE OF DAM	7
4.3 WARNING SYSTEM IN EFFECT	7
4.4 EVALUATION	7

	<u>PAGE NO.</u>
5 HYDROLOGIC/HYDRAULIC	8
5.1 DRAINAGE AREA CHARACTERISTICS	8
5.2 ANALYSIS CRITERIA	8
5.3 SPILLWAY CAPACITY	8
5.4 RESERVOIR CAPACITY	8
5.5 FLOODS OF RECORD	8
5.6 OVERTOPPING POTENTIAL	9
5.7 EVALUATION	9
6 STRUCTURAL STABILITY	10
6.1 EVALUATION OF STRUCTURAL STABILITY	10
7 ASSESSMENT/RECOMMENDATIONS	11
7.1 ASSESSMENT	11
7.2 RECOMMENDED MEASURES	11

APPENDIX

- A. PHOTOGRAPHS
- B. VISUAL INSPECTION CHECKLIST
- C. HYDROLOGIC/HYDRAULIC ENGINEERING DATA AND COMPUTATIONS
- D. STRUCTURAL STABILITY ANALYSES
- E. REFERENCES
- F. DRAWINGS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Mill Pond Dam (I.D. No. NY 368)
State Located: New York
County Located: Essex
Watershed: Lake Champlain Basin
Date of Inspection: April 16, 1980

ASSESSMENT

Examination of available documents and a visual inspection of the dam did not reveal conditions which constitute an immediate hazard to human life or property.

Several deficiencies were noted and these should be corrected within 6 months of the date of final approval of this report. Among the actions which should be taken are refilling the cribs which are missing material, repair of displaced timbers on the downstream face, replace broken timbers, repair of the valve on the drain, and repair of the spalling concrete on the wingwall which extends downstream of the north abutment. In addition, a detailed emergency action plan and warning system should be developed.


This dam does not have sufficient spillway capacity to adequately discharge the peak outflow from one-half the PMF. The analysis indicates that the dam would be overtopped by all storms exceeding 15% of the PMF. However, the structural stability analysis indicates that the dam would be stable when subjected to the PMF storm event. Therefore, the spillway is assessed as being inadequate.

The water surface level for either the PMF or one-half the PMF would result in flow around the northern end of the concrete wingwall which extends from the abutment of the dam. An accurate topographic survey should be performed where this end around flow is likely to occur. This survey should be completed within 6 months and modifications necessary to prevent the adverse effects of this flow should be made within 12 months.

George Koch

George Koch
Chief, Dam Safety Section
New York State Department
of Environmental Conservation
NY License NO. 45937


Approved By:



Col. W. M. Smith Jr.
New York District Engineer

Date:

28 AUG 1980



OVERVIEW
Mill Pond Dam
I.D. No. NY 368

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
MILL POND DAM
I.D. NO. NY 368
#201C-4289
LAKE CHAMPLAIN BASIN
ESSEX COUNTY, NEW YORK

SECTION 1: PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase I inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers, to fulfill the requirements of the National Dam Inspection Act, Public Law 92-367.

b. Purpose of Inspection

This inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, to determine if these deficiencies constitute hazards to life and property, and to recommend remedial measures where required.

1.2 DESCRIPTION OF PROJECT

a. Description of Dam

The Mill Pond Dam in Lake Placid is a structure composed of hemlock timber cribs, a gatehouse, and concrete walls extending beyond both ends of the dam.

The dam itself is 136 feet long and a maximum of 17.5 feet high. A steel sheet pile wall acts as a cutoff beneath the dam. The timber cribs are filled with cobbles and boulders and hemlock planks cover the cribs. The concrete walls extend 150 feet west from the southern end of the dam and 100 feet north beyond the gatehouse on the northern end.

The spillway consists of two steps and is located in the center of the dam. The lower level is 57 feet long. The second level is stepped 1.5 feet above the first and is a total of 92.5 feet long. The gatehouse at the northern end of the dam contains the control mechanism for a valve which regulates flow at the reservoir drain inlet, an 84 inch diameter steel. A 42 inch diameter reinforced concrete pipe forms the outlet to this pipe.

b. Location

The dam is located on the Chubb River within the limits of the Village of Lake Placid. Railroad Street (also known as Averyville Road) runs adjacent to the structure and NY Route 73 is approximately 1000 feet downstream of the dam.

c. Size Classification

The dam is 18 feet high and has a maximum storage capacity of 266 acre-feet. Therefore, the dam is in the small size category as defined by the

"Recommended Guidelines for Safety Inspection of Dams."

d. Hazard Classification

The dam is classified as "high" hazard due to the presence of several commercial establishments, an apartment building and a state highway located several thousand feet downstream of the dam.

e. Ownership

The dam is owned by the Village of Lake Placid, New York. Mr. John Barry a village trustee was contacted concerning the inspection. His telephone number is (518)523-2597.

f. Purpose of Dam

The dam is used to maintain the water surface of the Mill Pond for recreational purposes.

g. Design and Construction History

The dam as it now exists was constructed in 1978. It replaced another dam at this location which failed a number of years ago. Only the reservoir drain and gate house from the old structure were incorporated into the reconstructed dam. The new structure was designed by Spencer Thew, consulting engineer from Canton, New York

h. Normal Operating Procedures

There are no regular operating procedures for this structure.

1.3 PERTINENT DATA

a. Drainage Area (sq. mi.)

40.05

b. Discharge at Dam

Water Surface @:(cfs)

Spillway

Elev. 1729.44 2522

Spillway

Elev. 1725.5 276

Reservoir Drain - 42" pipe

Elev. 1725.5 208

c. Elevations (USGS Datum)

Top of Dam

1729.44

Top Step of Spillway

1725.50

Spillway Crest

1724.0

Invert of Drain (inlet)

1714.0

d. Reservoir-Surface Area (acres)

Top of Dam

28

Top Step of Spillway (Elev. 1725.5)

25

Spillway Crest (Elev. 1724)

22

e. Storage Capacity (acre-feet)

Top of Dam

266

Top step of spillway

137

Spillway Crest

88

f. Dam

Type: Timber crib dam composed of hemlock timbers which are filled with cobbles and boulders.

Dam length (ft):

137

Crest width (ft):

11

g. Spillway

Type - Two level overflow section in the center of timber cribs

Length (ft)	Lower level	57
	Upper level-total	92.5

h. Reservoir Drain

Type: 84 inch steel conduit with a valve at upstream end. Conduit connects with a 42 inch reinforced concrete pipe which forms the outlet.

i. Appurtenant Structures

1. Gatehouse - Rectangular building 17 ft. by 24 ft.; contains control mechanism for the reservoir drain
2. Concrete Walls - 2 walls-one extending from each end of structure
Wall at southern end is average of 8 feet high and extends 150 feet to the west. Wall at northern end is about 4 feet and extends northerly 100 feet beyond gatehouse.

SECTION 2: ENGINEERING DATA

2.1 GEOTECHNICAL DATA

a. Geology

The Mill Pond Dam is located in the high peaks section of the Adirondack Highlands physiographic province of New York State. The rock in this area dates from the Precambrian era. It has been intensely metamorphosed by heat, pressure, folding and faulting. Surface features of the rock reflect the effects of glaciation. A review of the "Brittle Structures Map of the State of New York" indicated that there are no faults in the immediate vicinity of the dam.

The surficial soils are the result of glaciations during the Cenozoic Era, the last of which was the Wisconsin glaciation.

b. Subsurface Investigations

Two borings were progressed at the site of this dam to provide subsurface information for the design. These holes indicated that the subsurface conditions consist of several feet of miscellaneous fill material underlain by sand and gravel. Logs from the two drill holes have been included in Appendix F.

2.2 DESIGN RECORDS

This dam was designed in 1977 by Spencer Thew, Consulting Engineer. Plans and other design information was available. Copies of selected sheets from the plans and a copy of the application for permit for the reconstruction of the dam have been included in Appendix F.

The designer of this structure made an error in delineating the drainage area and based the design on a drainage area of 16.55 square miles. As a result, the inflows for which the dam was designed were much smaller than the values which were calculated for this report.

2.3 CONSTRUCTION RECORDS

A set of as-built plans for the structure was available. In addition, reports from several inspections conducted by state officials during the construction were also available.

2.4 OPERATION RECORDS

No operation records are known to exist for this dam.

2.5 EVALUATION OF DATA

The data presented in this report was obtained from the Department of Environmental Conservation files and from a 1979 report titled "Hydroelectric Feasibility Study, Chubb River Sites", prepared by O'Brien & Gere Engineers, Inc. for the New York State Energy Research and Development Authority. The information available appeared to be adequate and reliable for Phase 1 inspection purposes.

SECTION 3: VISUAL INSPECTION

3.1 FINDINGS

a. General

Visual inspection of the Mill Pond Dam was conducted on April 16, 1980. The weather was overcast and the temperature was in the thirties. At the time of the inspection, water was flowing over the spillway at a depth of approximately 0.75 feet.

b. Dam

This dam was in satisfactory condition. However, several deficiencies were noted. Among these deficiencies were cribs that were not completely filled with stone and some displaced timbers on the downstream face.

The backfill in the cribs has been a maintenance problem since the dam was constructed in 1978. The cribs were originally filled with bank run gravel. Much of this material washed out during the initial filling of the pond. Additional quantities washed out each year. Each year cobbles and crushed stone are put into the cribs to replace the material which has washed out. Last year, 40 tons of stone was put into the cribs. At the time of the inspection, a number of cribs needed additional backfill material.

There were several timbers on the downstream face which had been displaced. One timber had come out of the crib and was at the base of the dam. Other timbers had displaced into the crib. There were also several broken planks on the second level of the timber cribs in the spillway.

c. Spillway

The spillway consisted of a two level channel section in the center of the dam. The tops of the cribs across the entire length of the dam were covered with hemlock planks. In the spillway section, water flowed across the planks and plunged onto the bottom level of cribs, whose tops had been left uncovered. With the exception of the backfilling problems, displaced logs, and broken planks previously mentioned, the spillway was in satisfactory condition.

d. Reservoir Drain

Visual observations of the reservoir drain were limited to an inspection of the outlet pipe. The valve is reported to be operational and was opened approximately 6 inches at the time of the inspection. Mr. Barry said that the valve will not close completely so there is always some flow through the conduit.

e. Concrete Walls

The concrete walls which extend from each end of the structure were in satisfactory condition. The wall at the southern end of the dam was constructed in 1978 and was in good condition. The wall which extends from the northern end of the dam consists of about 2.5 feet of new concrete on top of an existing wall. This entire wall extends for approximately 100 feet to the north and is in satisfactory condition. The wall terminates at this point but the top is several feet above the existing ground surface. As a result, the water could flow around the end of this wall before it would overtop the dam.

f. Gatehouse

The gatehouse was in satisfactory condition. It was being reconstructed and might be converted into a museum in the future.

g. Downstream Channel

The channel downstream of the dam contains large boulders, cobbles and gravel. A pool was formed immediately downstream of the dam in 1979 by excavating the gravel which had washed through the cribs. This pool helped to dissipate energy in the channel.

There was a wingwall which extended from the north abutment for about 20 feet along the channel. The concrete on this wall was spalling and deteriorated.

3.2 Evaluation of Observations

Visual inspection revealed several deficiencies on this structure. The following items were noted:

1. Several of the cribs were not completely filled with stone.
2. Some timbers on the downstream face were displaced.
3. The valve on the reservoir drain could not be closed completely.
4. The concrete wall at the northern end of the dam is not long enough to prevent water from flowing around the end of the structure.
5. The concrete on the wingwall which extended downstream from the north abutment was spalling and deteriorated.
6. Several broken planks on the second level of cribs.

SECTION 4: OPERATION AND MAINTENANCE PROCEDURE

4.1 PROCEDURES

There are no regular operation procedures for this dam.

4.2 MAINTENANCE OF DAM

Routine maintenance on the dam is performed by the Village of Lake Placid. The Village has an annual maintenance program which includes refilling the cribs, replacing any damaged timbers, and making other minor repairs as required.

4.3 WARNING SYSTEM IN EFFECT

No apparent warning system is present.

4.4 EVALUATION

The operation and maintenance procedures for this dam appear to be satisfactory.

SECTION 5: HYDROLOGIC/HYDRAULIC

5.1 DRAINAGE AREA CHARACTERISTICS

Delineation of the watershed for Mill Pond was made using the USGS 7.5 minute quadrangles for Lake Placid, Saranac Lake, and Ampersand Lake, New York. The drainage area for this dam is 40 square miles.

The northern portion of the drainage basin is dominated by Lake Placid. Mountain peaks rising up to 4800 feet form the outer limits of the drainage area. The slopes are generally steep throughout the watershed.

5.2 ANALYSIS CRITERIA

For the purposes of this analysis, the drainage area was divided into three subbasins. The first subbasin consisted of 20.89 square miles of forest and lake which make up the watershed to Lake Placid. The runoff from this basin was then routed through the dam on Lake Placid, taking the storage capacity in the lake into account. The time of concentration for this basin was then adjusted to account for the time it takes the water to reach Mill Pond. The second subbasin was a 3.87 square mile watershed immediately upstream of Mill Pond. The third subbasin consisted of 15.29 square miles which form the drainage area for the main branch of the Chubb River.

The analysis of the floodwater retarding capability of this dam was performed using the Corps of Engineers HEC-1 computer program, Dam Safety version. This program develops an inflow hydrograph using the "Snyder Synthetic Unit Hydrograph" method and then uses the "Modified Puls" flood routing procedure. The spillway design flood selected was the Probable Maximum Flood (PMF) in accordance with the Recommended Guidelines of the U.S. Army Corps of Engineers.

5.3 SPILLWAY CAPACITY

The spillway is located in the center of the dam. The spillway was analyzed as a broad crested weir consisting of two segments, each with discharge coefficients (c) ranging from 2.65 to 2.8. The computed discharge capacity of the spillway with the water surface at the top of the dam is 2522 cfs.

The discharge capacity of the drain was not included since the valve on this conduit is normally closed.

5.4 RESERVOIR CAPACITY

Storage capacity of the reservoir between the spillway crest and the top of the dam is 178 acre-feet, which is equivalent to a runoff depth of 0.1 inches over the entire 40 square mile drainage area. The total storage capacity of Mill Pond is 266 acre-feet. Lake Placid is the dominant feature of the northern subbasin of the watershed. It provides a substantial amount of storage which reduces the peak flows at the Mill Pond Dam.

5.5 FLOODS OF RECORD

No accurate information was available regarding the maximum known flood

at this structure. Mr. Barry indicated that the highest water surface in the pond was up to the middle of the top crib (approximately elevation 1727.5). The computed discharge for this water level is approximately 1200 cfs.

5.6 OVERTOPPING POTENTIAL

Analysis using the Probable Maximum Flood (PMF) and one-half the PMF indicates that the dam does not have sufficient spillway capacity. For a PMF peak outflow of 15,617 cfs, the dam would be overtopped to a depth of 5.03 feet. For the peak outflow from one-half the PMF of 7,616 cfs, the depth of overtopping would be 2.41 feet.

5.7 EVALUATION

Using the Corps of Engineer's screening criteria for initial review of spillway adequacy, it has been determined that the dam would be overtopped by all storms exceeding 15% of the PMF inflow. However, the structural stability analysis performed for this structure indicates that the dam would be stable when subjected to the PMF storm event. Therefore, the spillway is assessed as being inadequate.

Because the ground surface beyond the end of the wall at the northern end of the dam is below the level of the top of the dam, water would flow around the end of the wall during high water conditions. Further investigation of this condition is required.

SECTION 6: STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

Visual observation of the dam revealed several deficiencies which could affect the stability of the dam. There were some cribs which were missing rock backfill material and several timbers on the downstream face had been displaced. In addition, some of the planks on the spillway section of the dam were broken. Although these deficiencies were observed, the overall vertical and horizontal alignments appeared to be satisfactory.

b. Data Review and Stability Evaluation

This dam is a rock-filled timber crib structure. A stability analysis for the spillway section of the dam was performed using the as-built plans prepared by Spencer Thew, Consulting Engineer. The analysis assumed that the sheet piling was driven as indicated on the plans and was capable of providing passive resistance against sliding. The following conditions were analyzed.

- a. Normal conditions with reservoir level 0.5 feet above spillway crest (elevation 1724.5);
- b. Reservoir level 0.5 feet above spillway crest with an ice load of 10,000 lb/ft;
- c. PMF, water flowing over the top of dam at a depth of 5.03 feet.

The analyses performed indicate that the factors of safety against overturning and sliding are as follows:

<u>Case</u>	<u>Factors of Safety</u>	
	<u>Overturning</u>	<u>Sliding</u>
a. Reservoir at Elev. 1724.5	17.27	6.27
b. Same as (a) plus an ice load of 10,000 lb/ft	2.35	2.09
c. PMF, water at 5.03 feet over top of dam	4.91	2.05
d. Reservoir at Elev. 1724; with seismic	6.03	4.40

The results of these analyses indicate that the structure is stable. However, the stability analyses performed only checked the overall stability of the structure acting as a mass. It is beyond the scope of this report to assess the integrity of the connections between the individual timber members of the structure and their ability to withstand the forces to which they are subjected.

d. Seismic Stability

This dam is located in Seismic Zone 2. A seismic stability analysis was performed for the structure in accordance with Corps of Engineers guidelines and using a seismic coefficient of 0.10. The analysis indicated acceptable factors of safety for both overturning and sliding.

SECTION 7: ASSESSMENT/RECOMMENDATIONS

7.1 ASSESSMENT

a. Safety

The Phase 1 inspection of the Mill Pond Dam did not reveal conditions which constitute a hazard to human life or property. However, several deficiencies were noted which should be corrected. Cribs need to be refilled and displaced logs should be repaired. The wingwall downstream of the north abutment should be repaired, since failure of this wall could affect the reservoir drain.

b. Adequacy of Information

The information available for the preparation of this report was considered to be adequate for Phase 1 inspection purposes.

c. Need for Additional Investigations

A topographic survey of the area at the northern end of the dam, especially in the area beyond the end of the concrete wall, should be performed. This survey will provide information concerning the end-around potential for flow in this area.

d. Urgency

The deficiencies noted in the following section should be corrected within 6 months of the date of final approval of this report. The required survey should also be completed within 6 months and necessary modifications to this end of the dam made within 1 year.

7.2 RECOMMENDED MEASURES

1. Refill any cribs which are not completely filled with stone.
2. Repair the displaced timbers on the downstream face of the dam.
3. Repair the valve on the penstock so it will operate properly.
4. Make modifications necessary to prevent flood waters from flowing around the northern end of the dam.
5. Repair the spalling and deteriorated concrete on the wingwall which extends along the downstream channel from the north abutment.
6. Replace broken planks on the spillway section.
7. Develop an emergency action plan for notification of downstream residents.

APPENDIX A

PHOTOGRAPHS




Concrete Wall which Extends from South Abutment



Concrete Wall which Extends from North Abutment



South Abutment of Dam



Sheet Piling Extending Through Upper
Spillway Crib on South Abutment




North Abutment, Gatehouse, and Deteriorated Wingwall




Close-Up View of Deteriorated Wingwall



Stepped Spillway Channel



Gatehouse and 42 inch Outlet to Reservoir Drain Conduit



Water Flowing Through Dam and into Lower Cribs



Water Flowing Directly into the Lower Cribs



Water Flowing Through Dam
Note Displaced Timber on Lower Crib



Close-Up View of Displaced Timber Shown Above

APPENDIX B

VISUAL INSPECTION CHECKLIST

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam MILL POND DAM
Fed. I.D. # N.Y. 368 DEC Dam No. 201C-4289
River Basin LAKE CHAMPLAIN
Location: Town NORTH ELBA County ESSEX
Stream Name CHUBB RIVER
Tributary of AUSABLE RIVER
Latitude (N) 44° 17.0' Longitude (W) 73° 59'
Type of Dam TIMBER CRIB WITH CRUSHED STONE BACKFILL
Hazard Category C
Date(s) of Inspection 4/16/80
Weather Conditions 30° OVERCAST & SNOW
Reservoir Level at Time of Inspection 0.75' ABOVE 8/ST STEP OF SALL-CREST

b. Inspection Personnel R. WARRENDER W. LYNICK

c. Persons Contacted (Including Address & Phone No.) JOHN BARRY VILLAGE
TRUSTEE LAKE PLACID, NEW YORK

d. History:

Date Constructed 1978 Date(s) Reconstructed ~~1979~~

Designer SPENCER THEU, CANTON, NEW YORK

Constructed By _____

Owner VILLAGE OF LAKE PLACID

NO EMBANKMENT - THEREFORE SKIPPED NO. 2.

(1) Erosion at Contact _____

(2) Seepage Along Contact _____

3) Drainage System

a. Description of System TIMBER CRIB-ROCKFILL-VERY POROUS-ALLOWS
FLOW THRU DAM - NO ACTUAL DRAINAGE SYSTEM.

b. Condition of System _____

c. Discharge from Drainage System _____

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs,
Piezometers, Etc.) NONE

5) Reservoir

- a. Slopes GRASS TREES AND NATURAL ROCK LINED BANKS
- b. Sedimentation NONE APPARENT
- c. Unusual Conditions Which Affect Dam NONE

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) LARGE APARTMENT BUILDING, SEVERAL RESTAURANTS & STATE RTE. 73
- b. Seepage, Unusual Growth NO
- c. Evidence of Movement Beyond Toe of Dam NO
- d. Condition of Downstream Channel LARGE BOULDER FILL & WALLED SECTION DOWN PAST ROUTE 73 BRIDGE

7) Spillway(s) (Including Discharge Conveyance Channel)

NOTCHED TIMBERS (HEMLOCK-CREOSOTED) WITH 2X12 TIMBER PLANK DECK - VERTICAL INCLINED UPSTREAM PLANKING ON FACE

- a. General TIMBER PLANKING IS FLEXIBLE IN SOME SPOTS DUE TO THE REMOVAL OF FILL MATERIAL FROM CRIB
THE 2ND SECTION FROM THE NORTH END - 2ND CRIB WAS MISSING MORE MATERIAL THAN ANY OTHERS
- b. Condition of Service Spillway SATISFACTORY - ENTIRELY SUBMERGED
ONE TIMBER FROM LEVEL NO. 4 IS DISPLACED, NO SUBSIDENCE OR MISALIGNMENT - TIMBER PLANK DECK - OK - SOME OF BACKFILL MATERIAL IS MISSING

c. Condition of Auxiliary Spillway NONE - POTENTIAL FOR EROSION AROUND
EXTREME LEFT OF CONCRETE WALL - (NORTHERN END OF DAM)

d. Condition of Discharge Conveyance Channel DOWNSTREAM POOL
FILL ENCROACHMENT FROM LEFT (NORTHERN) SIDE OF STREAM
CHANNEL. POOL WAS DEEPENED AFTER GRAVEL FILL WASHED THROUGH
THE DAM & FILLED DOWNSTREAM CHANNEL - DREDGING WAS USED
TO REMOVE THIS MATERIAL.

8) Reservoir Drain/Outlet

Type: Pipe _____ ^{PENSTOCK} Conduit 7' DIA - Other 42" DIA PCPE EXTENSION
THRU NEW GRAVEL & BOULDER FILL

Material: Concrete _____ Metal STEEL Other _____

Size: 7' DIAMETER TO 42" Length _____

Invert Elevations: Entrance _____ Exit _____

Physical Condition (Describe): _____ Unobservable ✓

Material: _____

Joints: _____ Alignment _____

Structural Integrity: _____

Hydraulic Capability: WAS OPENED SLIGHTLY & CLEAR WAS
PASSING AT TIME OF INSPECTION

Means of Control: Gate ✓ Valve _____ Uncontrolled _____

Operation: Operable ✓ Inoperable _____ Other _____

Present Condition (Describe): REPORTED THAT IT IS NOT
POSSIBLE TO FULLY CLOSE THE GATE

9) Structural

- a. Concrete Surfaces NORTH ABUTMENT - 20" TOP WIDTH CONCRETE WALL
SOME CONCRETE CRACKING & SPALLING AT DOWNSTREAM END OF WING WALL
NORTH ABUT. WALL HAS NEW CONCRETE CAP 3' HIGH ON TOP OF OLD WALL
SOUTH ABUT. WALL - ENTIRELY NEW - BOTH THESE WALLS ARE IN GOOD SHAPE
- b. Structural Cracking NONE OBSERVED
- c. Movement - Horizontal & Vertical Alignment (Settlement) NONE NOTED
- d. Junctions with Abutments or Embankments. NORTH ABUTMENT - IRREGULAR
BACKFILL - HOLES & DEPRESSIONS ALONG DOWNSTREAM END OF ABUTMENT
WALL
SOUTH ABUTMENT - SATISFACTORY
- e. Drains - Foundation, Joint, Face NONE
- f. Water Passages, Conduits, Sluices RESERVOIR DRAIN - PASSES THROUGH
NORTH ABUTMENT
- g. Seepage or Leakage SUBSTANTIAL LEAKAGE THROUGH CRIBS - AS
WOULD BE EXPECTED - AT NORTHERN END SEEPAGE COMES THROUGH
1ST CRIB & PLOTTES INTO A GAP AT UPSTREAM END OF SECOND CRIB.
FLOOD HAS REMOVED SOME MATERIAL - SEVERAL CRIBS ARE MISSING
BACKFILL MATERIAL

h. Joints - Construction, etc. _____

i. Foundation _____

j. Abutments OKAY

k. Control Gates NONE

l. Approach & Outlet Channels SATISFACTORY

m. Energy Dissipators (Plunge Pool, etc.) TIMBER CRIB & DEEPEMED
TAILWATER POOL

n. Intake Structures _____

o. Stability _____

p. Miscellaneous FENCING ALONG TOP OF ABUTMENT WALLS IS OKAY

10) Appurtenant Structures (Power House, Lock, Gatehouse, Other)

a. Description and Condition _____

GATEHOUSE - CONTAINS CONTROL MECHANISM

FOR RESERVOIR DRAIN VALVE - VILLAGE IS

IN THE PROCESS OF RECONSTRUCTING THE OUTSIDE

OF THE BUILDING - STRUCTURALLY THE BUILDING IS

IN GOOD CONDITION.

APPENDIX C
HYDROLOGIC/HYDRAULIC
ENGINEERING DATA AND COMPUTATIONS

CHECK LIST FOR DAMS
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

1

AREA-CAPACITY DATA:

	<u>Elevation</u> (ft.)	<u>Surface Area</u> (acres)	<u>Storage Capacity</u> (acre-ft.)
1) Top of Dam	<u>1729.44</u>	<u>22</u>	<u>246</u>
2) Design High Water (Max. Design Pool)	<u> </u>	<u> </u>	<u> </u>
3) Auxiliary Spillway Crest	<u>1700.5</u>	<u>25</u>	<u>137</u>
4) Pool Level with Flashboards	<u>1700</u>	<u> </u>	<u> </u>
5) Service Spillway Crest	<u>1700.0</u>	<u>22</u>	<u>22</u>

DISCHARGES

	<u>Volume</u> (cfs)
1) Average Daily	<u> </u>
2) Spillway @ Maximum High Water	<u>7412</u>
3) Spillway @ Design High Water	<u> </u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>216</u>
5) Low Level Outlet	<u>212</u>
6) Total (of all facilities) @ Maximum High Water	<u> </u>
7) Maximum Known Flood	<u>1000</u>

CREST:

ELEVATION: 1000Type: ConcreteWidth: 10' Length: 100'Spillover 10' x 10' x 10'Location _____

SPILLWAY:

PRINCIPAL

EMERGENCY

1000 Elevation 1000Concrete Type Concrete5' Width 100'Type of ControlUncontrolled

Controlled:

Type
(Flashboards; gate)NumberSize/LengthInvert MaterialAnticipated Length
of operating serviceChute LengthHeight Between Spillway Crest
& Approach Channel Invert
(Weir Flow)

OUTLET STRUCTURES/EMERGENCY DRAWDOWN FACILITIES:

Type: Gate _____ Sluice _____ Conduit _____ Penstock _____

Shape : _____

Size: _____

Elevations: Entrance invert _____

Exit Invert _____

Tailrace Channel: Elevation _____

HYDROMETEROLOGICAL GAGES:

Type : _____

Location: _____

Records:

Date - _____

Max. Reading - _____

FLOOD WATER CONTROL SYSTEM:

Warning System: _____

Method of Controlled Releases (mechanisms):

DRAINAGE AREA: 4,000 Acres

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: ForestTerrain - Relief: SlopingSurface - Soil: Red ClayRunoff Potential (existing or planned extensive alterations to existing
(surface or subsurface conditions))
NonePotential Sedimentation problem areas (natural or man-made; present or future)
NonePotential Backwater problem areas for levels at maximum storage capacity
including surcharge storage:
NoneDikes - Floodwalls (overflow & non-overflow) - Low reaches along the
Reservoir perimeter:

Location: _____

Elevation: _____

Reservoir:

Length @ Maximum Pool _____ (Miles)

Length of Shoreline (@ Spillway Crest) _____ (Miles)

PROJECT GRID

JOB	MILL FORD DAM	SHEET NO.	1	CHECKED BY		DATE	
SUBJECT	HYDROLOGIC/HYDRAULIC COMPUTATIONS	COMPUTED BY	RLW	DATE	5/15/20		
DRAINAGE AREA - ENTIRE BASIN 40.05 SQ. MI.							
AREA CAN BE DIVIDED INTO THREE SUBBASINS							
SUBBASIN No. 1 - AREA TO NORTH OF DAM							
DRAINAGE AREA OF LAKE PLACID							
AREA = 20.89 SQ. MI.							
SNYDER HYDROGRAPH PARAMETERS - SUB-BASIN 1							
$L = 7.20 \text{ mi}$				$L_{ca} = 2.25 \text{ mi}$			
FMP = 16.5 in				$C_L \rightarrow U = 2.0$			
$t_p = C - (L \cdot L_{ca})^3 = 2.0 [7.2 \cdot 2.25]^3 = 4.61 \text{ hrs}$							
$t_b = \frac{t_p}{5.5} = \frac{4.61}{5.5} = .84 \text{ Hours} - \text{Use } \frac{1}{2} \text{ hour increments}$							
$t_{pr} = 4.61 + .25(5.5 - .84) = 4.53$							
WIF # 33 PIF: RAIN = $h - L$							
ZC: 1 FMP RAIN = 16.5 IN (200 mi ² - 24 hr)							
6 hr = 102%				24 hr = 124%			
12 hr = 114%				48 hr = 133%			
$TRSF = 1 - \frac{.20}{(45.07)^{.9718}} = .855$							
BASE FLOW ZCFS/GPM = $2(20.89) = 41.78$ USE HQFS							

PROJECT GRID

JOB	MILL FORD LAMP	SHEET NO.	2	CHECKED BY		DATE	
SUBJECT	H-250-0-0-0 / H-250-0-0-0 COMPUTATIONS			COMPUTED BY	RLW	DATE	5/1/80

ENTIRE COMPUTATIONS FOR LAKE PLANK LAMP

W.S. AT ELEV. 1858.67

$$Q = CLH^{3/2} = 2.6(3)(.67)^{3/2} = 4.3 \text{ cfs} \approx 5 \text{ cfs}$$

W.S. AT ELEV. 1861

$$Q = CLH^{3/2} + C_2 L_2 H_2^{3/2} = 2.6(3)(3)^{3/2} + (2.6)(137)(2.33)^{3/2}$$

$$Q = 40 + 1267 = 1307 \text{ cfs} \approx 1300 \text{ cfs}$$

SURFACE AREA COMPUTATIONS - TAKEN FROM MAP OF LAKE

PLANIMETERED VALUES - LAKE SURFACE

LAKE SURFACE	= 29.37 in ²
BUCK ISLAND	= 3.01 in ²
MOOSE ISLAND	= 4.50 in ²
	21.36 in ²

SURFACE AREA AT ELEV. 1857 = $(21.36 \text{ in}^2) / (111.47 \text{ in}^2/\text{acre}) = 2379 \text{ ACRES}$

PLANIMETERED VALUES - DEPTH OF 20' BELOW LAKE SURFACE

LAKE AREA	18.83
MOOSE ISLAND	5.21
	13.62 in ²

SURFACE AREA AT ELEV. 1837 = 1517 ACRES

PROJECT GRID

JOB	MILL FORD DAM	SHEET NO.	2A	CHECKED BY		DATE	
SUBJECT	HYDROLOGIC / FLOODING COMPUTATIONS			COMPUTED BY	RLW	DATE	5.13.78
STORAGE CAPACITY COMPUTATIONS							
CAPACITY AT ELEVATION 1837							
$V = \pi R^2 \frac{h}{3} = (2379 \text{ ACRES}) \left(\frac{150'}{3} \right) = 118,950 \text{ AC-FT}$							
CAPACITY AT ELEVATION 1837							
$V = (15117 \text{ AC}) \left(\frac{132'}{3} \right) = 65,737 \text{ AC-FT}$							
CAPACITY AT ELEVATION 1861							
SURFACE AREA = 2574 AC							
$V = (2574) \left(\frac{150'}{3} \right) = 132,132 \text{ AC-FT}$							

PROJECT GRID

JOB	MILL Pond DAM	SHEET NO.	3	CHECKED BY		DATE	
SUBJECT	HYDROLOGIC / HYDRAULIC COMPUTATIONS			COMPUTED BY	RLW	DATE	6/9/80
SUBBASIN NO. 2 - CENTER PORTION OF DRAINAGE AREA							
AREA = 3.87 mi ²							
SNYDER HYDROGRAPH PARAMETERS - SUBBASIN 2							
L = 3.4 mi L _{ca} = .7 mi							
PMP = 16.5 in C ₁ → USE 2.0							
$t_t = 2.0 [3.4 + .7]^3 = 2.60$							
$t_r = \frac{2.60}{5.5} = .47$ USE 1/2 HOUR							
$t_p = 2.60 + .25(.47 - .5) = 2.59$							
$TRSPC = 1 - \frac{.3808}{(400 \text{ mi}^2)} = .978 = .855$							
BASEFLOW → USE 40 cfs							

PROJECT GRID

JOB	1A - 1.0 LA	SHEET NO.	4	CHECKED BY		DATE	
SUBJECT	HYDROLOGIC/HYDROLOGIC			COMPUTED BY	RLW	DATE	5/15/80

SUB AREA 11C.3 - SOUTHERN PORTON - LARVAE AREA

Area = 15.29 mi²

SAMPLE HYDROLOGIC PARAMETERS - SUB AREA 3

L = 4.40 mi L_u = 4.90

T_u = 16.5 C_u → V_u = 2.0

$t_p = (2.48) \left[\frac{4.40 \cdot 4.90}{15.29} \right]^{0.3} = 6.31$

$t_p = \frac{1}{5} \cdot \frac{6.31}{5.5} = 1.15$ Use = $\frac{1}{5}$ Use 4.5. 5.5. 4

$t_p = 16.31 + .25(1.15 - .5) = 16.60$

TRFPC = $1 - \frac{.5}{(16.60 - 16.31)} = .975 = .855$

BASE = 40 cfs 2 cfs/cu. = 2(19.18) = 38.36 Use 40 cfs

PROJECT GRID

JOB MILL FORD DAM	SHEET NO. 5	CHECKED BY	DATE
SUBJECT HYDRAULIC COMPUTATIONS		COMPUTED BY RLW	DATE 5/20/51

MILL FORD DAM - OUTFLOW COMPUTATIONS

ELEVATION	H	C	Q	H	C	Q	H	C	Q	Q TOTAL
1724	0	+	+	+	+	+	+	+	+	0
1725.5	1.5	2.66	276.1	0	+	+	+	+	+	276.1
1727	3	2.7	793	1.5	2.65	121	+	+	+	914
1727	4	2.75	1243	2.5	2.65	259	+	+	+	1502
1727	5	2.79	1762	3.5	2.65	430	+	+	+	2192
1729.44	5.44	2.8	2327	3.94	2.66	515	0	+	+	2842
1730	6	2.8	2825	4.5	2.66	629	.96	2.6	132	3117

STAGE-STORAGE DATA TAKEN FROM PERMIT APPLICATION

PENSTOCK DISCHARGE CAPACITY

DIAMETER AT OUTLET = 42" $A = \pi \left(\frac{42}{2} \right)^2 = 1385$

$Q = A \sqrt{\frac{2gH}{1 + K_e + K_v + K_f L}}$
 $= 9.62 \sqrt{\frac{2(32.2)H}{1 + 0 + 0 + .00784(40)}}$

ELEV	H	Q
1724	8	190
1725.5	9.5	208
1729.44	13.44	345

[illegible]

ASCVII DE SECT OF F SLSGP STUDS CALCULATIONS
SUBREP BY P. CARP AT SUBR1
OFFICE OF CARP AT SUBR1
SUBOFF BY P. CARP AT SUBR2
SUBOFF BY P. CARP AT SUBR3
COUNTRY A BY P. CARP AT SUBR4
SUBOFF BY P. CARP AT SUBR5
SUBOFF BY P. CARP AT SUBR6

NEW YORK STATE
DEPT OF ENVIRONMENTAL CONSERVATION
FLEET PROTECTION BUREAU

ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED
DATE 01-11-2001 BY 60322 UCBAW/SJS

[illegible]

MULTI-PLAN ANALYSES TO BE PERFORMED	
PLANES	RATIOS
1	1.00
2	0.50
3	0.15

[illegible]

SUB-AREA RUN-TIME COMPUTATION

LAFLOR HYDROGRAPH SUBBASIN 1
ISTAQ ICUMIP O ITCNW O ITAPE C JULT 2 JPRT C INAME I STAGE 0 I AUTO 0

HYDROGRAPH DATA		RATIOS		LOCAL	
TIME	STAGE	TRSDA	TRSPC	ISNOV	ISAME
1	23.89	40.07	0.06	0	1

SPFE	PJS	R6	PRFCIF DATA			R72	R96
%			R12	Q24	R46	C.	C.
16.50		95.00	104.00	110.00	125.00		

LUNGS DATA										
LFIGHT	ST-KR	DLTPK	RTINL	EPAIN	STANS	RTIOK	STRYL	CASTL	ALSHX	RTIMP
C.	C.	0.	1.00	0.	%	1.00	1.00	0.10	0.	C.
0		0.								

UNIT HYDROGRAPH DATA
TPO 4.5J CP=0.63 NTAM C

```

APPROXIMATE CLAP COEFFICIENTS FACT. GIVEN SHOCK CP AND TP ARE TC=10.00 AND Q= 0.33 INTERVALS
STATS= 40.00 QCSH= 40.00 RTICR= 1.00
RECESSION DATA

```

UNIT HYDROGRAPH	50 PERCENT OF DEPENDENT ORDINATES	LAG	4.50 PCLRS	CP	VL	1.00
224.	511.	930.	1677.	1040.	1918.	1894.
1526.	1374.	1213.	849.	753.	668.	592.
406.	913.	324.	255.	226.	201.	178.
140.	12.	110.	77.	69.	60.	53.
42.	57.	31.	23.	20.	18.	16.

DATE	PERIOD	EXCS	LOSS	EX-OF-PRIND	FLOW	PR-VA	PERICU	KAIN	EXCS	LCSS	GNP C
10-20	10-20	0.00	0.00	0.00	1.02	14.00	76	0.00	0.75	0.05	2940.
1-1	1-20	0.00	0.00	0.00	1.02	14.00	77	1.01	0.66	0.05	3689.
1-1	1-20	0.00	0.00	0.00	1.02	15.00	78	1.01	0.96	0.05	4665.

[illegible]

HYDROGRAPH AT STA 50+00 FOR PLAN 1, RTIC 1

TIME	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
20.	3220.	2757.	1143.	408.	58761.
21.	91.	77.	34.	12.	1564.
22.		1.21	2.11	2.18	2.18
23.		30.82	53.34	55.36	55.39
24.		1343.	2347.	2427.	2427.
25.		1690.	2895.	2994.	2995.
26.					
27.					
28.					
29.					
30.					
31.					
32.					
33.					
34.					
35.					
36.					
37.					
38.					
39.					
40.					
41.					
42.					
43.					
44.					
45.					
46.					
47.					
48.					
49.					
50.					
51.					
52.					
53.					
54.					
55.					
56.					
57.					
58.					
59.					
60.					

HYDROGRAPH AT STA 50+01 FOR PLAN 1, RTIC 2

TIME	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
20.	10735.	9025.	3945.	1360.	195869.
21.	304.	246.	112.	38.	5546.
22.		4.02	7.83	7.27	7.27
23.		102.08	178.46	184.52	184.52
24.		4475.	7624.	8090.	8090.
25.		5520.	9651.	9978.	9984.
26.					
27.					
28.					
29.					
30.					
31.					
32.					
33.					
34.					
35.					
36.					
37.					
38.					
39.					
40.					
41.					
42.					
43.					
44.					
45.					
46.					
47.					
48.					
49.					
50.					
51.					
52.					
53.					
54.					
55.					
56.					
57.					
58.					
59.					
60.					

HYDROGRAPH AT STA 50+02 FOR PLAN 1, RTIC 3

TIME	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
20.	10735.	9025.	3945.	1360.	195869.
21.	304.	246.	112.	38.	5546.
22.		4.02	7.83	7.27	7.27
23.		102.08	178.46	184.52	184.52
24.		4475.	7624.	8090.	8090.
25.		5520.	9651.	9978.	9984.
26.					
27.					
28.					
29.					
30.					
31.					
32.					
33.					
34.					
35.					
36.					
37.					
38.					
39.					
40.					
41.					
42.					
43.					
44.					
45.					
46.					
47.					
48.					
49.					
50.					
51.					
52.					
53.					
54.					
55.					
56.					
57.					
58.					
59.					
60.					

PEAK	9-HFUR	24-HFUR	72-HFUR	TOTAL VOLUME
C4S	18050.	7869.	2719.	28638.
C4S	511.	223.	77.	1151.
1-C4S	8.04	14.05	14.53	14.54
H ₂	204.15	356.52	369.05	369.23
AC-FI	8950.	15666.	16179.	16181.
TOTAL C4.4	11040.	19301.	19957.	19957.

HYDROGRAPH REUTIG

RECTEE PARAGRAPH THROUGH LAKE PLACID

STAGE	1058.00	1858.70	1861.00
FLW	0.	5.00	1300.00
CAPACITY#	0.	118950.	132132.
ELEVATION#	1707.	1857.	1861.

TYPEL	CO-DO	EXPD	DAMPHIC
1851.0	3.0	1.5	15C.

STATION: DA.1, PLAN 1, RATIC 1

40-OF-PERIOD HYDROGRAPH CORRECT

1015

•

22

2

22

٢٠

52

44

25

21.

[illegible]

圖書在版編目(CIP)數據

2074

STATION: CAPL, PLAN 1, RATIC 2
END-OF-PERIOD HYDROGRAPH ORDINATES

PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VELOCITY
122246	122249	122251	122250	122251	122252
122254	122257	122259	122258	122259	122260
122262	122265	122266	122266	122267	122268
122270	122271	122274	122274	122275	122276
122278	122280	122282	122283	122283	122284
122286	122287	122290	122291	122292	122293
122294	122296	122300	122301	122302	122303
122298	122300	122305	122305	122306	122307
122306	122308	122312	122312	122313	122314
122314	122316	122320	122320	122321	122322
122322	122324	122328	122328	122329	122330
122330	122332	122336	122336	122337	122338
122338	122340	122344	122344	122345	122346
122346	122348	122352	122352	122353	122354
122354	122356	122360	122360	122361	122362
122362	122364	122368	122368	122369	122370
122370	122372	122376	122376	122377	122378
122378	122380	122384	122384	122385	122386
122386	122388	122392	122392	122393	122394
122394	122396	122400	122400	122401	122402
122402	122404	122408	122408	122409	122410
122410	122412	122416	122416	122417	122418
122418	122420	122424	122424	122425	122426
122426	122428	122432	122432	122433	122434
122434	122436	122440	122440	122441	122442
122442	122444	122448	122448	122449	122450
122450	122452	122456	122456	122457	122458
122458	122460	122464	122464	122465	122466
122466	122468	122472	122472	122473	122474
122474	122476	122480	122480	122481	122482
122482	122484	122488	122488	122489	122490
122490	122492	122496	122496	122497	122498
122498	122500	122504	122504	122505	122506
122506	122508	122512	122512	122513	122514
122514	122516	122520	122520	122521	122522
122522	122524	122528	122528	122529	122530
122530	122532	122536	122536	122537	122538
122538	122540	122544	122544	122545	122546
122546	122548	122552	122552	122553	122554
122554	122556	122560	122560	122561	122562
122562	122564	122568	122568	122569	122570
122570	122572	122576	122576	122577	122578
122578	122580	122584	122584	122585	122586
122586	122588	122592	122592	122593	122594
122594	122596	122600	122600	122601	122602
122602	122604	122608	122608	122609	122610
122610	122612	122616	122616	122617	122618
122618	122620	122624	122624	122625	122626
122626	122628	122632	122632	122633	122634
122634	122636	122640	122640	122641	122642
122642	122644	122648	122648	122649	122650
122650	122652	122656	122656	122657	122658
122658	122660	122664	122664	122665	122666
122666	122668	122672	122672	122673	122674
122674	122676	122680	122680	122681	122682
122682	122684	122688	122688	122689	122690
122690	122692	122696	122696	122697	122698
122698	122700	122704	122704	122705	122706
122706	122708	122712	122712	122713	122714
122714	122716	122720	122720	122721	122722
122722	122724	122728	122728	122729	122730
122730	122732	122736	122736	122737	122738
122738	122740	122744	122744	122745	122746
122746	122748	122752	122752	122753	122754
122754	122756	122760	122760	122761	122762
122762	122764	122768	122768	122769	122770
122770	122772	122776	122776	122777	122778
122778	122780	122784	122784	122785	122786
122786	122788	122792	122792	122793	122794
122794	122796	122800	122800	122801	122802
122802	122804	122808	122808	122809	122810
122810	122812	122816	122816	122817	122818
122818	122820	122824	122824	122825	122826
122826	122828	122832	122832	122833	122834
122834	122836	122840	122840	122841	122842
122842	122844	122848	122848	122849	122850
122850	122852	122856	122856	122857	122858
122858	122860	122864	122864	122865	122866
122866	122868	122872	122872	122873	122874
122874	122876	122880	122880	122881	122882
122882	122884	122888	122888	122889	122890
122890	122892	122896	122896	122897	122898
122898	122900	122904	122904	122905	122906
122906	122908	122912	122912	122913	122914
122914	122916	122920	122920	122921	122922
122922	122924	122928	122928	122929	122930
122930	122932	122936	122936	122937	122938
122938	122940	122944	122944	122945	122946
122946	122948	122952	122952	122953	122954
122954	122956	122960	122960	122961	122962
122962	122964	122968	122968	122969	122970
122970	122972	122976	122976	122977	122978
122978	122980	122984	122984	122985	122986
122986	122988	122992	122992	122993	122994
122994	122996	123000	123000	123001	123002
123002	123004	123008	123008	123009	123010
123010	123012	123016	123016	123017	123018
123018	123020	123024	123024	123025	123026
123026	123028	123032	123032	123033	123034
123034	123036	123040	123040	123041	123042
123042	123044	123048	123048	123049	123050
123050	123052	123056	123056	123057	123058
123058	123060	123064	123064	123065	123066
123066	123068	123072	123072	123073	123074
123074	123076	123080	123080	123081	123082
123082	123084	123088	123088	123089	123090
123090	123092	123096	123096	123097	123098
123098	123100	123104	123104	123105	123106
123106	123108	123112	123112	123113	123114
123114	123116	123120	123120	123121	123122
123122	123124	123128	123128	123129	123130
123130	123132	123136	123136	123137	123138
123138	123140	123144	123144	123145	123146
123146	123148	123152	123152	123153	123154
123154	123156	123160	123160	123161	123162
123162	123164	123168	123168	123169	123170
123170	123172	123176	123176	123177	123178
123178	123180	123184	123184	123185	123186
123186	123188	123192	123192	123193	123194
123194	123196	123200	123200	123201	123202
123202	123204	123208	123208	123209	123210
123210	123212	123216	123216	123217	123218
123218	123220	123224	123224	123225	123226
123226	123228	123232	123232	123233	123234
123234	123236	123240	123240	123241	123242
123242	123244	123248	123248	123249	123250
123250	123252	123256	123256	123257	123258
123258	123260	123264	123264	123265	123266
123266	123268	123272	123272	123273	123274
123274	123276	123280	123280	123281	123282
123282	123284	123288	123288	123289	123290
123290	123292	123296	123296	123297	123298
123298	123300	123304	123304	123305	123306
123306	123308	123312	123312	123313	123314
123314	123316	123320	123320	123321	123322
123322	123324	123328	123328	123329	123330
123330	123332	123336	123336	123337	123338
123338	123340	123344	123344	123345	123346
123346	123348	123352	123352	123353	123354
123354	123356	123360	123360	123361	123362
123362	123364	123368	123368	123369	123370
123370	123372	123376	123376	123377	123378
123378	123380	123384	123384	123385	123386
123386	123388	123392	123392	123393	123394
123394	123396	123400	123400	123401	123402
123402	123404	123408	123408	123409	123410
123410	123412	123416	123416	123417	123418
123418	123420	123424	123424	123425	123426
123426	123428	123432	123432	123433	123434
123434	123436	123440	123440	123441	123442
123442	123444	123448	123448	123449	123450
123450	123452	123456	123456	123457	123458
123458	123460	123464	123464	123465	123466
123466	123468	123472	123472	123473	123474
123474	123476	123480	123480	123481	123482
123482	123484	123488	123488	123489	123490
123490	123492	123496	123496	123497	123498
123498	123500	123504	123504	123505	123506
123506	123508	123512	123512	123513	123514
123514	123516	123520	123520	123521	123522
123522	123524	123528	123528	123529	123530
123530	123532	123536	123536	123537	123538
123538	123540	123544	123544	123545	123546
123546	123548	123552	123552	123553	123554
123554	123556	123560	123560	123561	123562
123562	123564	123568	123568	123569	123570
123570	123572	123576	123576	123577	123578
123578	123580	123584	123584	123585	123586
123586	123588	123592	123592	123593	123594
123594	123596				

STATION 0411, PLAC 1, RATIC 3
END-OF-PERIOD HYDROGRAPH CREINATES

PEAK OUTFLO. IS 2482. AT TIME 54.50 HOURS

	PEAK	6-HMP	24-HMP	72-HMP	TOTAL VOLUME
CFS	2482.	2454.	2166.	876.	126182.
CMS	70.	69.	61.	25.	3573.
1-CFS		1.06	3.66	4.68	4.68

00/000

SUB-AREA RUNOFF COMPUTATION

HYDROGRAPH SCENARIO 2
 ISTAT ICOMP I-CUR I-TAPE JPLT JPRI INAME I-STATE I-AUTO
 SCRRZ 0 0 0 2 C 1 0 0

HYDROGRAPH DATA
 TAREA TRSPC RATIO ISNUX ISAME LUCAL
 1 1 3.37 0 40.07 0.86 0 0 1 0

PRECIP DATA
 R12 R24 R48 R72 R96
 10.50 95.00 105.60 119.00 125.00 0 0

LOSS DATA
 L-UPD STRKR ULTKR ATIDL FRATN STNKS RTIDK STRTL CNSTL ALSMX RTIMP
 0 C 0 1.00 0 0 1.00 1.00 0.10 0 0

UNIT HYDROGRAPH DATA
 TP= 2.59 CP=0.63 NTA= C

RECESSION DATA
 STATQ= 40.10 QFCSN= 40.00 RTICR= 1.00
 APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SNYDER CP AND TP ARE TC= 6.10 AND R= 4.63 INTERVALS

UNIT HYDROGRAPH 28 END-OF-PERIOD ORIGINATES, LAG= 2.58 I-CURS, CP= 0.63 VOL= 1.00
 46. 166. 497. 584. 607. 541. 437. 352. 283.
 226. 148. 119. 96. 77. 62. 50. 40. 32.
 26. 17. 14. 11. 9. 7. 6.

MD.DA	PERIOD	RAIN	EXCS	LOSS	END-OF-PERIOD FLOW	CONP	FR.PN	PERIOD	RAIN	EXCS	LESS	CORP C
1.01	0.30	0.00	0.00	0.00	40.	40.	14.00	76	0.80	0.75	0.05	1077.
1.01	1.00	0.00	0.00	0.00	40.	40.	14.30	77	1.01	0.96	0.05	1438.
1.01	1.30	0.00	0.00	0.00	40.	40.	15.00	78	1.01	0.96	0.05	1855.
1.01	2.00	0.00	0.00	0.00	40.	40.	15.30	79	1.22	1.17	0.05	2293.
1.01	2.30	0.00	0.00	0.00	40.	40.	16.00	80	3.87	3.82	0.05	2857.
1.01	3.00	0.00	0.00	0.00	40.	40.	16.30	81	0.94	0.89	0.05	3602.
1.01	3.30	0.00	0.00	0.00	40.	40.	17.00	82	0.74	0.69	0.05	4418.
1.01	4.00	0.00	0.00	0.00	40.	40.	17.30	83	0.74	0.69	0.05	5129.
1.01	4.30	0.00	0.00	0.00	40.	40.	18.00	84	0.74	0.69	0.05	5585.
1.01	5.00	0.00	0.00	0.00	40.	40.	18.30	85	0.03	0.03	0.05	5683.
1.01	5.30	0.00	0.00	0.00	40.	40.	19.00	86	0.03	0.03	0.05	5368.
1.01	6.00	0.00	0.00	0.00	40.	40.	19.30	87	0.03	0.03	0.05	4798.
1.01	6.30	0.01	0.01	0.01	40.	40.	20.00	88	0.03	0.03	0.05	5368.
1.01	7.00	0.01	0.01	0.01	40.	40.	20.30	89	0.03	0.03	0.05	4163.
1.01	7.30	0.01	0.01	0.01	40.	40.	21.00	90	0.03	0.03	0.05	3512.
1.01	8.00	0.01	0.01	0.01	40.	40.	21.30	91	0.03	0.03	0.05	2697.
1.01	8.30	0.01	0.01	0.01	40.	40.	22.00	92	0.03	0.03	0.05	2367.
1.01	9.00	0.01	0.01	0.01	40.	40.	22.30	93	0.03	0.03	0.05	1939.
1.01	9.30	0.01	0.01	0.01	40.	40.	23.00	94	0.03	0.03	0.05	1595.
1.01	10.00	0.01	0.01	0.01	40.	40.	23.30	95	0.03	0.03	0.05	1318.
1.01	10.30	0.01	0.01	0.01	40.	40.	23.60	96	0.03	0.03	0.05	1095.
1.01	11.00	0.01	0.01	0.01	40.	40.	24.00	97	0.03	0.03	0.05	916.
1.01	11.30	0.01	0.01	0.01	40.	40.	24.30	98	0.03	0.03	0.05	770.
1.01	12.00	0.01	0.01	0.01	40.	40.	25.00	99	0.03	0.03	0.05	649.
1.01	12.30	0.01	0.01	0.01	40.	40.	25.30	100	0.03	0.03	0.05	547.
1.01	12.60	0.01	0.01	0.01	40.	40.	26.00	100	0.03	0.03	0.05	458.

[illegible]

	PEAK	0-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	852.	029.	229.	AC.	11614.
CFS	24.	18.	6.	2.	329.
INCHES		1.51	2.20	2.32	59.09
IN		38.42	55.92	58.94	480.
AC-FT		312.	434.	479.	552.
FT-DLS CU "4		385.	565.	590.	

Travis County

[illegible]

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
CFS	2841.	2058.	703.	269.	38712.	38712.
CIS	NO.	59.	22.	8.	1056.	1056.
INCHES		5.04	7.34	7.73	7.75	7.75
IN'		128.04	186.40	158.45	156.96	156.96
AC-FT		1040.	1514.	1556.	1600.	1600.
THIN S CL, M		1293.	1867.	1968.	1973.	1973.

WILLIS TOWERS WATSON

[illegible]

	PEAK	C- ¹³ NMR	72-HPLC	TOTAL
CPA	96.0%	41.86	536.	77425.
CPB	101.	119.	15.	2192.
ICPMS		10.04	15.47	15.51
IM		250.16	392.51	393.02
AC-FY		2040.	3151.	3158.
TRAILS CL M		2560.	3936.	3940.

5UR-AR-A RU:7FF COMPUTATION

INFLUENCE OF HYDROGRAPH SURFACES ON 3

ISTAD	ICOMP	IFCNC	ITAPE	JPLT	JPR7	INAME	ISTAGE	IAUTO
SI 513	0	0	0	2	C	1	0	0

HYDROGRAPH DATA		RATIO		ISANE		LOCAL	
TIME	TEMP	TRSDA	TRSPC	ISAW	ISAN	ISAW	ISAN
1	15.29	40.07	0.86	0	1	0	0

SPFE	W'S	PRECIP DATA
0.	16.50	R12
	95.00	R24
		108.00
		119.00

LRPT	STWR	DLTKR	RTINL	ERAIN	SPRKS	RTICK	STATL	CNSTL	ALSHX	RTIMP
0	G.	0.	1.00	0.	0.	1.00	1.00	0.10	0.	0.

UNIT HYDROGRAPH DATA
6.60 CPE0.63 NTAF C

APPROXIMATE CLARK COEFFICIENTS FROM
 STATUS= 40.60 QRCSEN= 40.50 RTICR= 1.00
 RECESSID. DATA
 GIVEN SNYDER CP AND TP ARE TC=14.47 ZAC R=12.22 INTERVALS

UNIT HYDROGRAPH 73 END-OF-PERIOD ORIGINATES, LAG= 6.61 HOURS, CP= 6.63 VOL= 1.00									
15.	243.	343.	450.	561.	671.	770.	849.		
748.	752.	923.	856.	768.	720.	669.	617.		
523.	482.	403.	377.	348.	320.	295.	272.		
231.	213.	196.	166.	153.	141.	130.	120.		
102.	94.	86.	73.	68.	62.	57.	53.		
45.	41.	34.	32.	30.	27.	25.	23.		
20.	14.	17.	14.	13.	12.	11.	10.		
5.	0.								

PERIOD	RR, CM	PERIOD	RAIN	EXCS	LOSS	COMP, %	FLDN	PERIOD	RAIN	EXCS	LOSS	COMP, %	FLDN	PERIOD	RAIN	EXCS	LOSS	COMP, %	FLDN
1.00	0.30	1	0.00	0.	0.00	40.	1.02	76	0.80	0.75	0.00	40.	1.02	76	0.80	0.75	0.00	40.	1.02
1.01	1.00	2	0.00	0.	0.00	40.	1.02	77	1.01	0.96	0.00	40.	1.02	77	1.01	0.96	0.00	40.	1.02
1.01	1.00	3	0.00	0.	0.00	40.	1.02	78	1.01	0.96	0.00	40.	1.02	78	1.01	0.96	0.00	40.	1.02
1.01	2.00	4	0.00	0.	0.00	40.	1.02	79	1.22	1.17	0.00	40.	1.02	79	1.22	1.17	0.00	40.	1.02
1.01	2.00	5	0.00	0.	0.00	40.	1.02	80	3.87	3.82	0.00	40.	1.02	80	3.87	3.82	0.00	40.	1.02
1.01	3.00	6	0.00	0.	0.00	40.	1.02	81	0.94	0.89	0.00	40.	1.02	81	0.94	0.89	0.00	40.	1.02
1.01	3.00	7	0.00	0.	0.00	40.	1.02	82	0.94	0.89	0.00	40.	1.02	82	0.94	0.89	0.00	40.	1.02
1.01	4.00	8	0.00	0.	0.00	40.	1.02	83	0.74	0.60	0.00	40.	1.02	83	0.74	0.60	0.00	40.	1.02

[illegible]

SIN 17.01 14.38 3.25 205065.
 (440.1) (365.1) (83.1) (8157.09)

CFR	116.13.	0-100%	24-100%	72-100%	TOTAL VOLUME
CHS	334.	100.75.	55.74.	1998.	207980.
100%		302.	157.	57.	8155.
100%		6.49	13.52	14.59	14.40
100%		164.97	343.31	370.58	370.85
100%		5274.	11010.	41692.	11900.
100%		6529.	13510.	14664.	14678.

THUS CHS

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL	VOLUME
CPS	1771.	1661.	633.	306.	43157.	
CNS	50.	65.	74.	6.	1223.	
LOC-HS		0.97	2.03	2.19	58.63	
SP		24.74	51.50	55.59	1785.	
AC-FT		754.	1632.	1784.	2262.	
THOUS CU M		979.	2038.	2200.		

	PEAK	6-HRUP	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	5904.	5338.	2777.	959.	143050.
CNS	167.	151.	79.	26.	4077.
INCLES		3.25	6.76	7.30	7.30
HA		82.43	171.66	165.30	185.43
AC-FY		2647.	3508.	5946.	5950.
THOLS CUM		3265.	6795.	7334.	7339.

[illegible]

[illegible]

PEAK OUTFLUX IS 2192. AT TIME 45.30 HOURS

STATION: MILLP, PLAN 1, RATIC 2

END-OF-PERIOD HYDROGRAPH CRICINATES

STORAGE

[illegible]

PLAN FLOW AND STORAGE (PLAN OF REGION) SUMMARY FOR MULTIPLE PLAN-RATIO ECLIPSE COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA 1, SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS		
				RATIO 1	RATIO 2	RATIO 3
				0.15	0.50	1.00
HYDROGRAPH AT	SUBST	20.00 (0.134 21)	1	3220.	10735.	21409.
			(91.19)	(303.97)	(607.94)
ROUTED TO	PUMP	20.00 (0.384 19)	1	22.	131.	2442.
			(0.81)	(23.53)	(70.29)
HYDROGRAPH AT	SUBST	3.87 (0.132 21)	1	152.	2441.	5013.
			(24.14)	(80.45)	(160.91)
HYDROGRAPH AT	SUBST	15.29 (0.132 21)	1	1771.	5904.	11018.
			(50.15)	(167.17)	(334.37)
3 COMBINED	CUMUL	40.05 (0.424 20)	1	2213.	7629.	15627.
			(62.13)	(215.94)	(442.51)
ROUTED TO	PUMP	40.05 (0.102 21)	1	2192.	7616.	15617.
			(62.07)	(215.67)	(442.72)

SAFETY ANALYSIS

PLATE 1									
ELEVATION		INITIAL VALUE		SPILLWAY CREST		TOP OF DAM		TIME OF FAILURE	
ST. AGE		1843.00		1843.00		1841.00		HOURS	
OUTFLOW		122246.0		122246.0		122132.0		CFS	
ASPCO		MAXIMUM		MAXIMUM		MAXIMUM		HOURS	
R-SECOEIN		DEPTH		OUTFLOW		OVER TOP		CFS	
0.5 FLEV		OVER DAM		CFS		HOURS		CFS	
1358.73		0.		22.		0.		0.	
1460.17		0.		831.		0.		0.	
1462.13		1.13		2452.		29.00		54.50	
P-R		MAXIMUM		STORAGE		DURATION		TIME OF	
0.15		AC-FT		AC-FT		OVER TOP		MAX OUTFLOW	
0.50		124649.		124649.		HOURS		HOURS	
1.00		129305.		133670.		CFS		CFS	


SUMMARY OF DAM SAFETY ANALYSIS

.....									
ELEVATION		INITIAL VALUE		SPILLWAY CREST		TLP OF DAM			
STAGE		1724.00		1724.00		1729.40			
WATER		NO.		88.		265.			
		0.		0.		2492.			
CALC		MAXIMUM		ELEVATION		TIME OF		TIME OF	
RESERVOIR		OUTFLOW		OVER TOP		MAX DUTELCW		FAILURE	
ELEV		CFS		FOUFS		HOURS		HOURS	
.15		2192.		0.		45.00		0.	
0.50		7616.		15.50		44.50		0.	
1.00		15617.		28.50		44.50		0.	

APPENDIX D

STABILITY COMPUTATIONS

STEELWAY SECTION



SCALE 1" = 10'

SEGMENT	AREA	DISTANCE TO CENTROID
1	$(\frac{6+12}{2})(12) = 108$	30.34
2	$(12)(8) = 96$	21
3	$(9.5)(8) = 76$	13
4	$(2)(9) = 18$	4.5

INPUT TO STABILITY ANALYSIS PROGRAM

<u>INPUT ENTRY</u>	<u>PROGRAM No.</u>
Unit Weight of Dam (K/ft^3)	0
Area of Segment No. 1 (ft^2)	1
Distance from Center of Gravity of Segment No. 1 to Downstream Toe (ft)	2
Area of Segment No. 2 (ft^2)	3
Distance from Center of Gravity of Segment No. 2 to Downstream Toe (ft)	4
Area of Segment No. 3 (ft^2)	5
Distance from Center of Gravity of Segment No. 3 to Downstream Toe (ft)	6
Base Width of Dam (Total) (ft)	7
Height of Dam (ft)	8
Ice Loading (K/L ft.)	9
Coefficient of Sliding	10
Unit Weight of Soil (K/ft^3)	11
Active Soil Coefficient - K_a	12
Passive Soil Coefficient - K_p	13
Height of Water over Top of Dam or Spillway (ft)	14
Height of Soil for Active Pressure (ft)	15
Height of Soil for Passive Pressure (ft)	16
Height of Water in Tailrace Channel (ft)	17
Weight of Water (K/ft^3)	18
Area of Segment No. 4 (ft^2)	19
Distance from Center of Gravity of Segment No. 4 to Downstream Toe (ft)	20
Height of Ice Load or Active Water (ft)	46

NORMAL CONDIT

ICE LOAD - 10,000 - 10

0.055 RCL
1
102.
102. RCL
2
30.3
30.3 RCL
3
96.
96. RCL
4
21.
21. RCL
5
76.
76. RCL
6
13.
13. RCL
7
0.
0. RCL
8
12.
12. RCL
9
0.
0. RCL
10
0.45
0.45 RCL
11
0.055
0.055 RCL
12
0.3
0.3 RCL
13
3.
3. RCL
14
0.
0. RCL
15
4.
4. RCL
16
1.
1. RCL
17
2.
2. RCL
18
0.0624
0.0624 RCL
19
18.
18. RCL
20
4.5
4.5 RCL
46
12.5

0.055 RCL
1
102.
102. RCL
2
30.3
30.3 RCL
3
96.
96. RCL
4
21.
21. RCL
5
76.
76. RCL
6
13.
13. RCL
7
0.
0. RCL
8
12.
12. RCL
9
10.
10. RCL
10
0.45
0.45 RCL
11
0.055
0.055 RCL
12
0.3
0.3 RCL
13
3.
3. RCL
14
0.
0. RCL
15
4.
4. RCL
16
1.
1. RCL
17
2.
2. RCL
18
0.0624
0.0624 RCL
19
18.
18. RCL
20
4.5
4.5 RCL
46
12.5

17.26817951

E.S. VS. C.V.E.T. FORM

2.348480052

19.9310523

12.14773973

4959883165

0.055	RCL	1
102.		
102.	RCL	2
30.3		
30.3	RCL	3
96.		
96.	RCL	4
21.		
21.	RCL	5
76.		
76.	RCL	6
13.		
13.	RCL	7
0.		
0.	RCL	8
12.		
12.	RCL	9
0.		
0.	RCL	10
0.45		
0.45	RCL	11
0.055		
0.055	RCL	12
0.3		
0.3	RCL	13
3.		
3.	RCL	14
11.		
11.	RCL	15
4.		
4.	RCL	16
1.		
1.	RCL	17
2.		
2.	RCL	18
0.0624		
0.0624	RCL	19
18.		
18.	RCL	20
4.5		
4.5	RCL	46
12.5		

0.055	RCL	1
102.		
102.	RCL	2
30.3		
30.3	RCL	3
96.		
96.	RCL	4
21.		
21.	RCL	5
76.		
76.	RCL	6
13.		
13.	RCL	7
0.		
0.	RCL	8
12.		
12.	RCL	9
0.		
0.	RCL	10
0.45		
0.45	RCL	11
0.055		
0.055	RCL	12
0.3		
0.3	RCL	13
3.		
3.	RCL	14
0.		
0.	RCL	15
4.		
4.	RCL	16
1.		
1.	RCL	17
2.		
2.	RCL	18
0.0624		
0.0624	RCL	19
18.		
18.	RCL	20
4.5		
4.5	RCL	46
12.5		
12.5	RCL	50
0.1		

4.917285605 <

16.85379203

P.S. vs. CYCLOTRON

6.030156011

17.64780666

PROJECT GRID

JOB MILL POND DAM	SHEET NO. 1	CHECKED BY	DATE
SUBJECT STRUCTURAL STABILITY ANALYSIS		COMPUTED BY RLW	DATE 5/6/80

ADJUST THE SLIDING RESISTANCES TO ACCOUNT FOR THE EFFECT OF THE SHEET PILE

1. CALCULATE PRESSURE DUE TO SHEET PILING

$\phi = 33^\circ$
 $K_a = 0.29$
 $K_p = 3.39$
 $\gamma_{sub} = 55 \text{ #/cf}$

LOADS

ACTIVE

① $3(0.55)(0.29)(17) = 8.85$

② $3(0.55)(3.39)(17) = 9.52$

④A $(3.5)(0.624)(7) = 1.53$

④B $(\frac{1}{2})(7)(0.624) = 1.54$

⑤ $(0.624)(10)^2 = 6.24$

PASSIVE

③ $\frac{1}{2}(17)^2(0.55)(3.39 - 0.29) = 25.65$

$\Sigma F_x = 24.65 + 9.52 - 8.85 - 1.53 - 1.54 - 6.24$
 $= 24.01 \text{ K}$

PROJECT GRID

JOB MILL POND DAM		SHEET NO. 2	CHECKED BY	DATE
SUBJECT STRUCTURAL STABILITY ANALYSIS			COMPUTED BY RLW	DATE 5/6/80
2. ADD EFFECTS OF SHEET PILE INTO COMPUTER STABILITY RESULTS				
NORMAL CONDITIONS				
$F.S. = \frac{7.43 + 24.01}{5.0} = 6.27$				
ICE LOAD				
$F.S. = \frac{7.43 + 24.01}{15.11} = 2.09$				
PMF				
$F.S. = \frac{7.43 + 19.66}{12.24} = 2.05$				
SEASONAL CONDITIONS				
$F.S. = \frac{7.43 + 24.01}{2.5} = 11.41$				

APPENDIX E

REFERENCES

APPENDIX E


REFERENCES

- 1) U.S. Department of Commerce; Weather Bureau;
Hydrometeorological Report No. 33 - Seasonal Variation of the Probable
Maximum Precipitation East of the 105th Meridian for Areas from 10 to
1,000 Square Miles and Durations of 6, 12, 24, and 48 Hours, April 1956.
- 2) H.W. King and E.F. Brater, Handbook of Hydraulics, 5th edition,
McGraw-Hill, 1963.
- 3) University of the State of New York, Geology of New York, Education
Leaflet 20, Reprinted 1973.
- 4) Elwyn E. Seelye, Design, 3rd edition, John Wiley and Sons, Inc., 1960.
- 5) U.S. Department of the Interior, Bureau of Reclamations;
Design of Small Dams, 2nd edition (rev. reprint), 1977.

APPENDIX F


DRAWINGS

DAM SITE



VICINITY MAP
MILL POND DAM
I.D. NO. NY 368

DAM SITE



TOPOGRAPHIC MAP
MILL POND DAM
I.D. NO. NY 368

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
ALBANY, NEW YORK 12201

FOR DEPARTMENT USE ONLY

Application No. 516-12-0135-77

Dam No. 201C-4289

Watershed Chubb River

APPLICATION FOR PERMIT

FOR THE CONSTRUCTION, RECONSTRUCTION OR REPAIR OF A DAM OR OTHER
IMPOUNDMENT STRUCTURE UNDER ENVIRONMENTAL CONSERVATION LAW, SECTION 15-0503

Read instructions on the reverse side before completing this application. Please type or print clearly in ink.

1. NAME AND ADDRESS OF APPLICANT			2. NAME AND ADDRESS OF OWNER (if different from applicant)		
First Name	M.I.	Last Name	First Name	M.I.	Last Name
Village of Lake Placid			Street Address		
Street Address			Post Office		
301 Main Street			State		
Post Office			Zip Code		
Lake Placid			New York		
12946					
TYPE OF PROJECT		4. IS STATE-OWNED LAND TO BE USED?	5. PROPOSED STARTING DATE		EXPECTED COMPLETION DATE
<input type="checkbox"/> Construction	<input checked="" type="checkbox"/> Reconstruction	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No		May 1, 1977
<input type="checkbox"/> Repair				September 30, 1977	

OBJECT DESCRIPTION

LOCATION OF DAM		County	Town	Give distance and direction from commonly accepted landmark
Stream or Body of Water		Essex	North Elba	Located in the Newman section of the Village of Lake Placid
LOCATION ON U.S. GEOLOGICAL SURVEY MAP		8. PROPOSED USE FOR IMPOUNDED WATER		
Name of Map	Latitude	Longitude	9. STATE THE HEIGHT ABOVE SPILLCREST OF THE LOWEST PART OF THE IMMEDIATE UPSTREAM ADJOINING PROPERTY OR PROPERTIES	
Lake Placid	44° 17' N	73° 59' W	Business Development, Safety	
Quadrangle			Aesthetic, Recreational	
IS THIS PROPOSED POND OR LAKE PART OF A PUBLIC WATER SUPPLY?		11. SIZE OF AREA DRAINING INTO POND OR LAKE (Acres or Square Miles)		
If not, where is nearest downstream public water supply intake?		2 Feet		
<input type="checkbox"/> Yes		<input checked="" type="checkbox"/> No		
		16.5 sq. miles		

THE DRAINAGE AREA IS COMPOSED OF: (Total = 100%)

83 % Forest 5 % Cropland 5 % Pasture 5 % Swamp 2 % Suburban Lands 2 % Urban Lands

TYPE OF SPILLWAY		14. DESIGNER'S ESTIMATE OF CLASS OF HAZARD (As described in "Guidelines for Small Earth Dam Design")	
<input checked="" type="checkbox"/> Service Spillway - Auxiliary Spillway Combination with a diversion pipe with a wooden control gate		<input type="checkbox"/> Class "a" <input checked="" type="checkbox"/> Class "b" <input type="checkbox"/> Class "c"	
<input type="checkbox"/> Single Spillway		NOTE: Provide descriptive information on character of downstream area.	
<input type="checkbox"/> Pipe Riser ONLY			
<input type="checkbox"/> Other			

15a. SERVICE SPILLWAY INFLOW DESIGN FLOOD		15b. SERVICE SPILLWAY INFLOW DESIGN FLOOD	
Frequency 50 yr Flood Peak 1280 c.f.s. Runoff Volume 12 in.	Frequency 50 yr Flood Peak 1280 c.f.s. Runoff Volume 12 in.		

THE SINGLE SPILLWAY OR AUXILIARY SPILLWAY IS COMPOSED OF:

<input type="checkbox"/> Vegetated Earth	<input type="checkbox"/> Concrete	<input checked="" type="checkbox"/> Timber	<input type="checkbox"/> Rock-filled Crib	<input type="checkbox"/> Masonry	<input type="checkbox"/> Other
MAXIMUM VELOCITY WITHIN THE SINGLE OR AUXILIARY SPILLWAY		18. SINGLE OR AUXILIARY SPILLWAY DISCHARGE AT DESIGN HIGH WATER		19. TYPE OF ENERGY DISSIPATER PROVIDED ON SINGLE SPILLWAY	
4.8 f.p.s.		1340 c.f.s.		<input type="checkbox"/> Hydraulic Jump Basin <input checked="" type="checkbox"/> Drop Structure <input type="checkbox"/> Other	

POND OR LAKE WILL BE DRAINED BY MEANS OF		WATER WILL BE SUPPLIED TO RIPARIAN OWNERS DOWNSTREAM BY MEANS OF		HEIGHT OF DAM ABOVE STREAM BED	
Diversion pipe with wooden control gate		Continuous flow over the spillway or through diversion pipe		18 Feet	

AREA-CAPACITY DATA		ELEVATION, Referred To Assumed Benchmark		SURFACE AREA		VOLUME STORED	
Answer 1, 2 and 3, OR 1, 2, 4, 5							
1. Top of Dam	1730.5 Feet	28 Acres	266 Acro-Feet				
2. Design High Water	1729.0 Feet	27 Acres	216 Acro-Feet				
3. Single Spillway Crest	Feet	Acres	Acro-Feet				
4. Auxiliary Spillway Crest	1726.5 Feet	25 Acres	137 Acro-Feet				
5. Service Spillway Crest	1725.0 Feet	22 Acres	88 Acro-Feet				

TYPE OF ENERGY DISSIPATER AT OUTLET OF CONDUIT:		IS PIPE RISER PROVIDED WITH AN ANTI-VORTEX DEVICE?	
<input type="checkbox"/> Impact Basin	<input checked="" type="checkbox"/> Plunge Pool	<input type="checkbox"/> Yes <input type="checkbox"/> No NA	
<input type="checkbox"/> Hydraulic Jump Basin	<input type="checkbox"/> Other		

DRAWDOWN TIMES: Answer 1 and 2, or 1, 3 and 4

1. Has provision been made to evacuate 90% of the storage between the design high water and the spillway crest within fourteen days?		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
2. Can the single spillway evacuate 75% of the storage between the design high water and the spillway crest within 48 hours?		<input type="checkbox"/> Yes <input type="checkbox"/> No
3. Can the Service Spillway evacuate 75% of the storage between the auxiliary spillway crest and the Service Spillway crests within seven days?		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
4. Can the Service Spillway and the Auxiliary Spillway in combination evacuate the storage between the design high water and the auxiliary spillway crest within 12 hours?		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

19-2 (6/75)

Merly N-36

DEPT. OF ENVIRONMENTAL CONSERVATION

State the character of the bed and banks in respect to natural types of soil materials, hardness, perviousness, water bearing, effect of exposure to air and water, uniformity, etc.

The upper bed soil profile is indicated on the attached soil boring logs. A steel sheet piling wall is proposed to prevent piping under the dam.

A walk-over reconnaissance of the pond bed indicates that the soils are generally fine sands containing a high percentage of silt. The pond should be relatively impervious due to deposition of sediments from the previous impoundment.

Character of embankment fill material(s)?

Are there porous seams or fissures in the foundation of the proposed dam? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Method used to obtain the above soil data <input checked="" type="checkbox"/> Soil Borings <input type="checkbox"/> Test Pits	
DESIGN ENGINEER Name of Agency or Individual Spencer F. Thew, P.E./L.S.		P.E. License No. of Individual 043732	
26. CONSTRUCTION ENGINEER OR CONTRACTOR Name of Agency or Individual Spencer F. Thew, P.E./L.S.		P.E. License No. of Individual 043732	
Address Canton, New York 13617		Same	
Title			

ADDRESS OF OFFICIAL NEWSPAPER OF LOCALITY WHERE PROPOSED WORKS ARE LOCATED

The Lake Placid News Box 111, Lake Placid, New York 12946

CERTIFICATION

Application is hereby made to the Department of Environmental Conservation pursuant to Section 15-0503 of the Environmental Conservation Law.

I, the undersigned, certify that the above statements are true and agree that the issuance of the permit is based on the accuracy thereof. As a condition to the issuance of a permit, the applicant accepts full legal responsibility for all damage, direct or indirect, of whatever nature, whomever suffered, arising out of the project described herein and agrees to indemnify and save harmless the State from suits, claims, damages and costs of every name and description resulting from the said project.

Date

Signature

INSTRUCTIONS

1. Type or print in INK.
2. Five (5) copies of all papers including detail construction plans and specifications must be filed.
3. The plans and specifications submitted with the application must include the following information:
 - (a) A plan showing proposed dam, dam appurtenances, bench marks, topographic contours at dam and around the anticipated reservoir area, including 2-foot contours to 6 feet above high water level.
 - (b) A profile along the dam axis and a transverse section of the dam at its maximum height.
 - (c) A profile along the center line and transverse section, or sections, of the spillways including stilling basins, outlet work, and other details, if necessary, in design of the structures.
 - (d) A topographical plan to a suitable scale showing drainage area, normal water level in the lake or pond and owners property-line metes and bounds.
 - (e) Specifications for materials and methods of construction.
 - (f) A log of all soil information available to the design engineer or conservationist and location of drill holes, test pits or other foundation exploration, location of borrow area, horizontal and vertical controls, if necessary.
 - (g) Additional drawings should be included to clearly show all details of the proposed works.
4. NO WORK of construction, reconstruction or repairs of the structure or structures SHALL BE STARTED UNTIL A PERMIT therefor has been issued by the New York State Department of Environmental Conservation.
5. The design, preparation of plans, estimates and specifications and the supervision of the erection, reconstruction and repair of all the structures herein applied for shall be done by a licensed professional engineer, or in the case of farm ponds by an engineer or conservationist employed by a governmental agency cooperating with a soil conservation district, or by an engineer employed by the Department of Environmental Conservation.
6. The applicant must publish a "Notice of Application" except for certain minor projects where publication may be dispensed with at the discretion of the Local Permit Agent.
7. An information circular "Guidelines for Small Earth Dam Designs" is available upon request from the Department of Environmental Conservation or the Local Permit Agent.

This circular outlines hydrologic design criteria which should be utilized by your design engineer in the preparation of plans for each dam.
8. Samples of foundation, embankment and construction materials need not be furnished unless requested.



ATLANTIC TESTING LABORATORY

CANTON, NEW YORK

SUBSURFACE INVESTIGATION

Report No. L-159-7-76

CLIENT: Mill Pond Committee

Location of Boring See Plan Number
E69-A-3-77

PROJECT: Mill Pond Dam

Date, start 7/27/76 Finish 7/27/76

Boring No. B-1 Sheet 1 of 1

Ground Water Observations

Casing Hammer Sampler Hammer
Wt. lbs. Wt. 140 lbs.
Fall 1715.7 in. Fall 30 in.
Ground Elev. $2\frac{3}{4}$ I.D. Casing
I.D. H.S. Auger

Date	Time	Depth	Casing at
7/27/76	2:45	6.0'	10.0'
7/27/76	4:00	1.5'	Out

DEPTH	CASING BLOWS/FT.	SAMPLE NO.	DEPTH OF SAMPLE		TYPE SAMPLE	BLWS ON SAMPLER PER SAMPLER O.D.	DEPTH OF CHANGE	CLASSIFICATION OF MATERIAL		DEPTH
			FROM	TO				F - FINE M - MEDIUM C - COARSE	AND SOME LITTLE TRACE	
		1	0.0	2.0	SS	1-3-2-4	2.0	Brown cmf SAND; some SILT; trace f GRAVEL; trace ORGANIC (wet, non-plastic) FILL		
		2	2.0	4.0	SS	2-2-1-5	4.0	Brown c mf SAND; little SILT; trace mf GRAVEL; trace DECOMPOSED WOOD (wet, non-plastic) FILL		
		3	4.0	6.0	SS	9-5-7-8		Brownish Grey cmf SAND; little SILT; (, non-plastic)		
	Augers	4	6.0	8.0	SS	13-14-22-28	8.0	Ditto		
		5	8.0	9.5	SS	16-20-28		Brownish Grey cmf SAND; trace SILT (wet, non-plastic)		
		6	10.0	12.0	SS	4-12-22-36	12.0	Ditto		
		7	15.0	16.5	SS	34-43-89	30.0	Brownish Grey cmf SAND; little mf GRAVEL; little SILT (wet, non-plastic)		
30								Bottom Boring 30.0'		
								Encountered flowing sand at 12'		
								Material increased in denseness with depth from 12 to 30 feet.		

SS - OPEN END SAMPLE
M - MEDIUM GRAIN TUBE
P - PISTON TYPE SAMPLE

DRILLERS Richard Collins Jack DonBleyker



ATLANTIC TESTING LABORATORY

CANTON, NEW YORK

SUBSURFACE INVESTIGATION

Report No. L-159-7-76

CLIENT: Mill Pond Committee Location of Boring See Plan Number E69-A-3-77
PROJECT: Mill Pond Dam Date, start 7/28/76 Finish 7/28/76

Boring No. B-2 Sheet 1 of 1

Ground Water Observations

Casing Hammer Sampler Hammer
Wt. lbs. Wt. 140 lbs.
Fall 1714.5 in. Fall 30 in.
Ground Elev. ☒ 2 3/4 I.D. Casing
☒ I.D. H.S. Auger

Date	Time	Depth	Casing at
7/28/76	12:45	4.0'	6.0'
7/28/76	3:20	1.0'	Out


DEPTH	CASING SLOWSIDE	SAMPLE NO.	DEPTH OF SAMPLE		TYPE SAMPLE	BLOWS ON SAMPLED PER SAMPLER O.D.	DEPTH OF CHANGE	CLASSIFICATION OF MATERIAL F - FINE M - MEDIUM C - COARSE AND - 25-30% SOME - 30-35% LITTLE - 10-20% TRACE - 5-10%	REMARKS
			FROM	TO					
		1	0.0	2.0	ss	pushed	2.0	Dark Brown SILT; little mf SAND; trace mf GRAVEL; trace ORGANIC; trace DECOMPOSED WOOD (wet, non- plastic) FILL	
		2	2.0	4.0	ss	1-1-1-1	4.0	Dark Brown SILT; little ORGANIC; trace mf SAND; trace DECOMPOSED WOOD (wet, non-plastic) FILL	
		3	4.0	6.0	ss	1-3-2-1	6.0	Dark Brown SILT; little ORGANIC; little mf SILT; trace mf GRAVEL; trace GLASS/DECOMPOSED WOOD (saturated, non-plastic) FILL	
		4	6.0	8.0	ss	7-5-8-7	15.0	Brown c-mf SAND; little SILT; trace f GRAVEL (saturated, non-plastic)	
		5	15.0	16.0	ss	9-38		Dark Brown c-mf SAND; some SILT; little mf GRAVEL (saturated, non- plastic)	
			18.0	19.0	ss	74-83			
35							35.0	Bottom Boring 35.0'	
								Encountered flowing sand at 12'	
								Material increased in denseness with depth from 15 to 35 feet.	

SS - SOFT OPEN SAMPLE
S - LUNCH. SAMPLE TUBE
P - 1-1/2" TYPE GROUND

DRILLERS Richard Collins Jack DanBleyker



2



CONTRACT No. 1

ALL ELEVATIONS BASED
BENCH MARK NO. H 115-
OLD LOADING PLATFORM
PRISON RAILROAD STATION
ELEV. 1735.93

BUILDING

GRAVEL
PARKING AREA
1731.0

EXISTING
GATE HOUSE

EXISTING PIPE

EXISTING
CONCRETE
RETAINMENT WALL

RIVER

BASELINE

STA	ELEV
0+00	1722.39
0+25	1725.07
0+50	1725.51
0+75	1725.88
1+00	1726.31
1+25	1726.76
1+50	1726.76
1+75	1727.42
2+00	1727.74
2+25	1728.50
2+50	1728.65
2+75	1729.60
3+00	1730.85




ALL ELEVATIONS BASED ON USGS DATUM
BENCH MARK NO. H 115 NORTHEAST OF
OLD LOADING PLATFORM AT THE DELAWARE
HUDSON RAILROAD STATION
ELEV 1735.93


LOCATION MAP
LAKE PLACID, NY

RIVER

BUILDING



ALL ELEVATIONS
BENCH MARK NO.
OLD LOADING PL.
HUDSON RAILROAD
ELEV 1735.93



ALL ELEVATIONS BASED ON USGS DATUM
BENCH MARK NO. H 115 NORTHEAST OF
OLD LOADING PLATFORM AT THE DELAWARE
HUDSON RAILROAD STATION
ELEV 1735.93

LOCATION MAP
LAKE PLACID NY

RIVER

BUILDING

TO KEENE

AS BUILT 11-10-78

MILL POND DAM RECONSTRUCTION	
SCALE 1" = 20'	APPROVED BY
DATE 3-15-77	
VILLAGE OF LAKE PLACID	
ESSEX COUNTY	
STATE OF NEW YORK	

TOP OF DAM ELEV. 1730.5
1729.4

1730

RETAINING WALL
TO BE
CONSTRUCTED

DESIGN HIGH WATER = 1728.0

1728

SIDEWALK

AUXILIARY SPILLWAY
CREST ELEV. 1725.5
Q = 184

1726

SERVICE SPILLWAY CREST
ELEV. 1723.0 - 1724.0
Q = 316 CFS

1724

EXISTING
CONCRETE
RETAINING WALL

1722

1720

TIMBER CRIB

1718

1716

1714

1712

0 10 20 30 40 50 60 70 80 90

1

FOOTING

DATE: 10/1/54
HOUR: 11:00 AM
FOOTING: 100

7 - RETAINING WALL

STEEL
MANUALLY GATED PENSTOCK
PENSTOCK DIAMETER 7 FEET
SLOPE 0.01 APPROX. $n=0.012$
FLOW CAPACITY 630 CFS

DEPTH OF FOUNDATION
BELOW SURFACE UNKNOWN


PENSTOCK

0 90 110 120 130

2

AS BUILT 11-10-78

FOR LOSS OF TIME
...
...
ME ...
LATE ... NEW YORK



BOTH LOGS NOTCHED
AT BOTH ENDS

DETAIL A
LOC - DETAILS



UPSTREAM

PLAN VIEW

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NOT TO SCALE
SEE END

CONCRETE DETAILS



CONCRETE REINFORCEMENT
DETAILS - SEE
EXPLANATION AND SEE OVER
WITH REINFORCEMENT

THIS DRAWING LANGUAGE IS AT
THE END OF THE DRAWING
SEE END

CONCRETE REINFORCEMENT
DETAILS - SEE
EXPLANATION AND SEE OVER
WITH REINFORCEMENT

SHEET NO. 1
CONCRETE REINFORCEMENT
DETAILS - SEE
EXPLANATION AND SEE OVER
WITH REINFORCEMENT

PLAN VIEW

ELEV 1230.5

1224
ELEV 1226

ELEV 1227.713

ELEVATION FACING UPSTREAM


5

6

AS BUILT 11-10-78	
TOWER CARD 4	
REAR VIEW	
DATE	
BY	
REMARKS	

OF EARTH EARTH WITH
ON PLANKING

TO BE
REMOVED



ET. OWN

THURSDAY TO 30 - RETAINING WALL DETAIL

SCALE 1/4" = 1'-0"

EXISTING CONCRETE
BASE SLAB

HASH SACK

TIMBER GATE

EXISTING CONCRETE
RETAINING WALL

RIPRAP SUFFICIENT
TO PROTECT PENSTON

EXISTING WALL

ELEV. 1730.5

EXISTING SIDEWALK

EXISTING WALL

PLACE IN RETE BETWEEN
TUBE AND DAM AND
SET BACK WALL

TO BE
DOED BY THE

1-100

WHAT REAR FOR SEE DRAWING
DO. EXISTING TYP FOR NEW
RETAINING WALL

FILE

SHEET PILING CUT OFF ELEV 1740

SHEET PILING TIP

DATA

EXISTING PENSTOCK AT 40' ANGLE
IN ORDER TO BE USED FOR STEEL
AS REQUIRED ON THE JOINT

TIMBER CRIB TO RETAINING

THIS IS ULTIMATE
ACT 4 - LOCKS

EXISTING PENSTOCK

EXISTING GATE HOUSE FOUND TO
BE WITH CONCRETE

CUT EXISTING PIPE AND RELOCATE TO
THIS LOCATION
LENGTH TO BE DETERMINED BY
FIELD CONDITIONS

CONCRETE
ALL

SUFFICIENT
RECT PENSTOCK

END RAP DISTRICT
TO PROTECT PENSTOCK

STEEL SHEET PILING

3

TO BE CONSTRUCTED
CONCRETE RETAINING WALL

TOP OF WALL ELEV 1730.5
DRILL HOLES 3/4" DIA. X 8"
AND INSERT NO. 6 REBAR
NO. 4 REBAR AT 18"
NO. 4 REBAR AT 12"

EXISTING GATE HOUSE FOUNDATION

PLACE CONCRETE
BETWEEN TIMBER CRIB AND
EXISTING GATE HOUSE
FOUNDATION WALL

TOP OF
EXISTING
CONCRETE
RETAINING WALL
ELEV 1728

TEMPORARY SPILLWAY
DURING THE WINTERS OF 1976

STEEL SHEET PILING WAS CAST
IN CONCRETE RETAINING
WALL

ELEV. 740

SHORT PILING TIP ELEV 1694

DETAIL "D"

ONE TO RETAINING WALL CROSS SECTION DETAIL

GATEHOUSE FOUNDATION WALL

FILL WITH CONCRETE

EXISTING RETAINING WALL

FILL WITH Boulders

GRIBBING TO BE
DESIGNED AND
CONSTRUCTED
COATS OF CONCRETE

GRIBBING TO BE
DESIGNED WITH 8" DIA
TIMBER BOLLERS
AND 1/2" DIA
BOLLERS

ALL ABOUT

EXISTING CONCRETE
BASE WALL

DESIGN BACK

TIMBER GATE


EXISTING CONCRETE
RETAINING WALL

RIPTAP SUFFICIENT
TO PROTECT PENSTOCK

DETAIL "E"
EMERGENCY PENSTOCK SPILLWAY



CUT EXISTING PILE AT 45° ANGLE
REINFORCE WITH ONE PLATE STEEL
AS REQUIRED ON THE JOINT



THIS IS WHAT IT
ACTUAL LOOKS

TIMBER CRUI TO RETAINING WALL


EXISTING PILEHEAD

EXISTING BATHHOUSE FOUNDATION WALL
BUILT WITH CONCRETE

CUT EXISTING PIPE AND RELOCATE TO
THIS LOCATION
LENGTH TO BE DETERMINED BY
FIELD CONDITIONS



WIP-RAID SUFFICIENT
TO PROTECT PILEHEAD



CONTACT AREA

DETAIL "D"

SECTION CRIB TO RETAINING WALL CROSS SECTION DETAIL

EXISTING GATEHOUSE FOUNDATION WALL

FILL WITH CONCRETE

EXISTING RETAINING WALL

FILL WITH Boulders

CRIBBING TO BE
DETAINED AND
TREATED WITH TWO
COATS OF CRIBOTE

CRIBBING TO BE
FILLED WITH 6" DIA
DRAINAGE BOLLERS
AND SAND RUN
OFF


3' CLEAR
ALL AROUND


ELEV 174.12

1	2	3	4
5	6	7	8
9	10	11	12
13	14	15	16
17	18	19	20
21	22	23	24
25	26	27	28
29	30	31	32
33	34	35	36
37	38	39	40
41	42	43	44
45	46	47	48
49	50	51	52
53	54	55	56
57	58	59	60
61	62	63	64
65	66	67	68
69	70	71	72
73	74	75	76
77	78	79	80
81	82	83	84
85	86	87	88
89	90	91	92
93	94	95	96
97	98	99	100

CRIB TO BE
DETAINED AND
TREATED WITH TWO
COATS OF CRIBOTE

AS BUILT 11-10-78






EXISTING
CONCRETE
GATE HOUSE

EXISTING STEEL SHEET PILING

EXACT LOCATION TO BE DETERMINED
IN FIELD



SEE PLAN NO.
ACTING ABOVE CON.

PLAN VIEW
SCALE 1"=20'

2 NO. 6 BARS CONTINUOUS

NO. 4 BARS 12" O.C.

NO. 4 BARS 9" O.C.

RETAINING WALL DETAIL
STA 2+00 TO 1+25
SCALE 1"=10'

AS BUILT 11-16-78

MILL AND RECONSTRUCTION	
PROJECT NO.	DATE
BY	REV.
DATE	REV.
DATE	REV.
DATE	REV.